# **Microcircuit Failure Mechanisms and Anomalies**

This section describes failure mechanisms and anomalies of microcircuits. Use this section as a guide to design and select microcircuits.

#### Failure Mechanisms - General

Microcircuit manufacturers have long since learned to control and reduce failures in their wafer fabrication and hermetic package processes. However, the plastic encapsulated microcircuit (PEM) processes are still maturing with some problems still not controlled as well as users would like. The military now allows the use of consumer, industrial and automotive microcircuits in applications. Since PEMs are fairly new to the military, their reliability and performance over time remain the subject of scrutiny by both the manufacturers and users.


Consumer-grade PEMs are the riskiest microcircuit products used by the military. The main areas of study regarding their use are their unique failure mechanisms. Until studies are complete, designers should continue to monitor these parts and not assume there is complete freedom to use any microcircuit in any environment without concern for reliability. The risk should be minimized and the parts should still be monitored. Both producers and users in the military marketplace should know the potential failure mechanisms and anomalies of each microcircuit they plan to use. Because of the newness and risk PEMs place on the military industry, this section describes them in more detail.

Figure 1 shows recent failure mechanism breakdown data for packaged die at microcircuit manufacturer facilities.

The Naval Surface Warfare Center, Crane Division has been periodically assessing PEMs for over 25 years. For an example, they recently assessed over 3,000 PEMs for Trident Fire Control, Trident Navigation, CEC, Army Tank Command (TACOM), and the NAVSEA Parts Reliability and Derating Manual Programs from 1997 through 1999. Figure 2 shows the number of failed, marginal, and passing PEMs during this assessment period. The more common failures and anomalies found during this assessment are (1) improper moisturesensitivity-level of package, (2) contamination, (3) poor die-paddle construction, (4) poor wire-bonds, (5) voiding, and (6) delaminations. Having 30% of the total microcircuits either failing or being marginal enforces the obvious need for PEM assessments and monitoring.










Figure 2. PEM Assessment Results Source: NSWC-Crane Division

Table 1 and Table 2 cites some of the more common microcircuit failure mechanisms and anomalies with their probable causes.

Туре	Example	Most Likely Cause	See Figure
Chemical			12
	1. Corrosion	Moisture and Ionic.	12 9
	2. Contamination	Poor process control by MFR.	14
	3. Dendritic	Moisture, Bias, and exposed metal.	13
	Growth		10
		Current density in AI metallization.	
	4. Metal	Inter-reaction of dissimilar metals E.G.	
	Ivligration	Al-Au (Purple Plague).	
	5. Intermetallics		
	5. Internetanos	Metal exposed to oxygen.	
	6. Oxides		
Physical			
	1. Open Circuit	Loss of bond/wire integrity, or cracked	6
		die from overstress by	
		Thermal/Mechanical Shock, or Vibration,	
		or weakened interconnects from Bond	
		misplacement and from	
	2. Short Circuit	Corrosion/Electro Migration.	
		Loss/weakening of wire-bonds from	
		sweep during injection of molding	
		compounds.	
		Particle or interconnect wire, metallic	
		migration, dendritic growth-poor process	
		control.	
Function	1. Loss or	Electrical Overstress, ESD, Radiation,	
	Degrade	High Resistance Electrical Contact, High	
		Temperature Exposure.	

Table 1. Failure Mechanisms: Die/Interconnects

# **Chemical Failure Mechanisms**

Historic chemical failure mechanism concerns with hermetic seal microcircuits also apply to PEMs; for example corrosion, contamination, dendritic growth, metal migration, oxides and intermetallics. PEMs are even more likely to develop "Purple Plague" because of the wide use of Aluminum (Al) and Gold (Au) in their wire bond fabrication. Although PEM manufacturers now use greatly improved encapsulant, additives such as bromide (fire retardant) can introduce halogens which produce corrosion when combined with moisture - all plastic encapsulates absorb moisture. PEM manufacturers now use encapsulants with additives such as bromide (a fire retardant) which can introduce halogens that produce corrosion when combined with moisture. All plastic encapsulants absorb moisture and improperly cured encapsulants can result in excessive porosity and moisture absorption.

Туре	Example	Most Likely Cause	See Figure
Chemical			
	1. Corrosion	Salt or Harsh Atmosphere.	10, 11
	2. Porosity/Pin	Poor cure of Encapsulant by MFR.	1, 15,
	Holes	(Encapsulated IC); Inferior grade of metal	
	3. Solderability	(Hermetic IC).	16
	4. Marking	Poor finish by MFR. or Harsh Atmosphere.	
		High Temperature Exposure, Harsh	
		Atmosphere or Cleaning Agent.	
Physical			
	1. Leaks	Poor weld or braze by Mfr., Fatigue by	2, 3,
		Thermal/ Mechanical Shock or Vibration	
		(Hermitic seal IC).	
	2. Rupture -		4, 5,
	"Pop Corning"	Absorbed moisture expands during solder	
	Delaminations	operation (Encansulated Packages) poor	


Improperly cured encapsulant can result in excessive porosity and moisture absorption.

Delaminations	operation (Encapsulated Packages), poor	
	process control, Thermal Shock	7, 8
3. Lead Seal	(Encapsulated Packages).	
	Poor process control of Lead/Package seal	
	by MFR., Mechanical Fatigue from	
	Vibration to Temperature Cycling. (Both	
	Package Technologies).	


Table 2. Failure Mechanisms: Packages/Leads

Physical anomalies occur from other additives used to tailor package characteristics, e.g. hardness, temperature coefficients of expansion, and heat dissipation. When these additives are segregated from inadequate mixing, they can produce cracking, crazing, pinholes, delaminations and voiding, which again is conducive to excessive moisture absorption. Probably the most common problem encountered by users is the phenomena known as "pop corning". It is caused by the rapid expansion of moisture within the encapsulant during soldering. The moisture absorbed during storage and handling quickly turns to steam producing sufficient pressures to literally blow the package apart.


Typical examples of defects and anomalies are shown in Figures 3 through 18.




**Figure 3** C-SAM image of PEM with die-attach delaminations (white area) and poor material porosity causing fuzzy image.




**Figure 4** C-SAM images of PEM with delaminations (Red area)




**Figure 5** C-SAM images of PEMs. Top images show delaminations (Red area). Bottom images show porosity in–texture appearance is mottled.




**Figure 6** C-SAM image of PEM with poor die-attach (Red area) and delaminations (Yellow/Red area)




**Figure 7** C-SAM image of PEM with poor die-attach. Appears voided (Red area) and material has excessive porosity causing fuzzy image.




**Figure 8** Construction analysis photo of PEM. Wire-bond displacement weakening bond causing latent dis-bond failure.



**Figure 9** C-SAM image of PEM. "Pop-corning" effect caused damaged corner from vapor phase solder re-flow overheating.



# **Figure 10** Construction analysis Photo of PEM. "Pop-Corning" effect caused crack in plastic from vapor phase solder re-flow overheating.



# Figure 11

SEM photo of PEM. Contamination - Residue from halogen presence in package. Cause latent defect by accelerating corrosion and weakening bond.







Figure 12 Photo of PEM following Salt Spray test. Failures from excessive lead damage. Caused by Salt Spray.







**Figure 13** Photo of PEM. Loss of seal integrity at leadframe tabs of PEM. Allowed moisture/salt ingression during salt spray Test. Accelerated corrosion latent defect.




**Figure 14** C-SAM image of PEMs. Salt ingression into PEM following Salt Spray test. Cause latent corrosion defect. Same PEM as Figure 11.



**Figure 15** SEM photo of PEM with Kirkendall Voiding (Purple Plague)



**Figure 16** SEM photo of PEM with internal dendritic growth



**Figure 17** C-SAM images of PEMs with poor die-paddle attachment. Left images are initial scans. Center images are following pre-conditioning. Right images are following 50 hours of HAST.




Figure 18 C-SAM images of PEMs with poor Die-Attach. Left images are initial scans. Center images are following pre-conditioning. Right images are following 50 hours of HAST.