

Ex-Forrest Sherman (DD 931)


May 2010






Demilitarization work was accomplished in the 1990's prior to the ship going on donation hold. External paint system failure is widespread.





Fiberglass insulation failure





Throughout the ship, all internal painted surfaces and deck tiles are extensively deteriorated