

FORREST SHERMAN

DD 931

MAY 17, 2010



base of superstructure corrosion



admin space deck damage



admin space deck buckling



aft gun demilitarized



aft gun demilitarized



demilitarized gun



aft deck



base of superstructure starboard side

base of superstructure missing rivet heads





Crew berthing



bridge forward

bridge





close up watertight door
corrosion



corroded hatch aft deck by
stern



corrosion



corrosion



corrosion around watertight door



corrosion around watertight door



corrosion on cooling system piping



corrosion on cooling system piping



CPO mess

CPO mess





deck corrosion

deck lifting





dissimilar metal corrosion stateroom



engineering spaces



flex joint cover



flex joint cover



flex joint still watertight





Mess deck looking forward



metal corrosion



metal corrosion

oil leak overhead on mess deck





oil on deck leaking from anchor
windlass

oil on deck from anchor windlass





scullery space holes in superstructure



starboard side bridge



starboard side looking forward




stateroom



stbd railing and stanchions







water tight door corrosion



water tight hatch on stern



watertight hatch missing dogs



watertight hatch corrosion