DEPARTMENT OF THE NAVY
NAVAL SEA SYSTEMS COMMAND
INACTIVE SHIPS MANAGEMENT OFFICE
BLDG. 8Y ST JULIENS CREEK ANNEX
PORTSMOUTH, VIRGINIA 23702-1009

IN REPLY REFER TO
4770
Ser N32/035
15 MAY 14

From: Director, Naval Sea Systems Command, Inactive Ships Management Office, Portsmouth, VA 23702-1009

Subj: CHANGE TO SHIP DISMANTLEMENT PROGRAM REPORTING LETTER FOR EX-JARRETT (FFG 33)

Ref: (a) INACTSHIPMAINTO Bremerton ltr 4770 Ser 00/023 of 11 Oct 12

Encl: (1) Polychlorinated Biphenyl (PCB) Survey Report

1. Per reference (a), enclosure (1) provides updates to enclosure (3) of the basic letter. Remove enclosure (3) of the basic letter and insert enclosure (1) of this change action.

2. Point of contact for NAVSEA INACTSHIPMAINTO Bremerton is Mr. Ray Porter, email: raymond.porter@navy.mil, commercial: (360) 476-3510, or DSN: 439-3510. Point of contact for NAVSEA INACTSHIPOFF Portsmouth is Mrs. Anita Staton, email: anita.staton@navy.mil, commercial: (757) 485-6381 ext 320, or DSN: 386-6381 ext 320.

M. JONES

Copy to:
NAVSEA INACTSHIPOFF List III
NAVSEA INACTSHIPMAINTO Bremerton, WA

DATE: DECEMBER 29, 2011

POLYCHLORINATED BIPHENYL (PCB) SURVEY REPORT

SHIP/CRAFT: JARRETT HULL NO.: FFG-33

This report certifies that a survey for Electrical/Electronic components that may contain Polychlorinated Biphenyl's (PCB) has been accomplished onboard the above named Ship/Craft in accordance with INACTSHIPOFFINST 4770.3D with the following results:

_____ PCB Survey was accomplished and no known PCB containing transformers or capacitors were found onboard.

__X__ PCB Survey was accomplished and appropriate signs posted on transformers, capacitors and all other suspected electrical/electronic components that may contain PCB's, see attached pages. No leaking PCB containing components were found.

_____ PCB Survey was accomplished and appropriate signs posted on transformers, capacitors and all other suspected electrical/electronic components that may contain PCB's, see attached pages. All suspected leaking PCB containing components found are listed below.

W. E. Ellis
QA/Inspection Manager

G. M. Musick III
Project Manager

Encl(3)

EQUIPMENT NAME AND A. P. L.	UNIT	ITEM	NIIN IDENTIFICATION NUMBER	PCB ID NUMBER	LEAKS Y/N	COMPARTMENT LOCATIONS	QTY	STATUS
REC TRANS AN/SPS-55	8	TRANSFORMER		100 TO 101	N	01-180-0-C	2	A
PWR SUPPLY	4	TRANSFORMER		38	N	02-116-1-Q	1	A
SPG-51D 7750	1	TRANSFORMER		2	N	02-116-1-Q	1	A
SPG-51D NO ID	1	TRANSFORMER		3	N	02-116-1-Q	1	A
MK69 MOD1 NO ID	3	TRANSFORMER		36-37	N	02-116-1-Q	2	A