DATE: 25 APRIL 2014

POLYCHLORINATED BIPHENYL (PCB) SURVEY REPORT

SHIP/CRAFT: RANGER **HULL NO.: CV-61**

This report certifies that a survey for Electrical/Electronic components that may contain Polychlorinated Biphenyl's (PCB) has been accomplished onboard the above named Ship/Craft in accordance with INACTSHIPOFFINST 4770.3D with the following results:

__X__ PCB Survey was accomplished and no known PCB containing transformers or capacitors were found onboard. PCB items were removed and disposed of during SINK-EX preparation in 2004.

_____ PCB Survey was accomplished and appropriate signs posted on transformers, capacitors and all other suspected electrical/electronic components that may contain PCB's, see attached pages. No leaking PCB containing components were found.

_____ PCB Survey was accomplished and appropriate signs posted on transformers, capacitors and all other suspected electrical/electronic components that may contain PCB's, see attached pages. All suspected leaking PCB containing components found are listed below.

Verified By:
W. E. Ellis
QA/Inspection Manager

Approved By:
G. M. Musick III
Project Manager