NOTICE: *This list may be made available to suppliers or prospective bidders who require the list in furnishing supplies to the Military Departments. Reproduction or use of the list in whole or in part for other purposes is prohibited, and violation will be cause for removal from this list.*

QPL-15731-2
~~24 March 1952~~
SUPERSEDING
QPL-15731-1
23 April 1951

4/23/5
a.

**MILITARY QUALIFIED PRODUCTS LIST**

**OF**

**PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION**

MIL-P-15731

PLASTIC MIX, REFRACTORY (SUPERDUTY, FIRE-CLAY)

**All products listed herein have been qualified under the requirements for the product as specified in the latest issue of the applicable specification. Revisions of this list will be issued as necessary. The listing of a product does not release the manufacturer from compliance with the specification requirements.**

| Government Designation | Manufacturer's Designation | Test or Qualification Reference | Manufacturer's Name and Address |
|---|---|---|---|
| ---------- | B&W Plastic Moldable | EN28/L5/1878 | Babcock and Wilcox Co.<br>85 Liberty Street<br>New York 6, N.Y.<br>Plant: Augusta, Ga. |
| ---------- | Super Brikram | EN28/L5/4350 | General Refractories Co.<br>1520 Locust Street<br>Philadelphia 7, Pa.<br>Plant: St. Louis, Mo. |
| ---------- | Super Marine<br>Super L Marine<br>Pyramid | EN28/L5/1949<br>EN28/L5/3985<br>EN28/L5/7611 | Gladding, McBean and C<br>1275 Harrison Street<br>San Francisco, Calif.<br>Plants: Los Angeles, Ca<br>Lincoln, Calif.<br>do. |
| ---------- | Super Plastic N | EN28/L5/1872 | A.P. Green Fire Brick C<br>1008 Breckenridge Stree<br>Mexico, Missouri<br>Plant: Same address |
| ---------- | H-W Superduty Plastic | EN28/L5/4115 | Harbison Walker Refractories Company<br>Farmers Bank Bldg.<br>Pittsburgh 22, Pa.<br>Plant: Vandalia, Mo. |
| ---------- | Ironton Super No Joint | EN28/L5/1945 | The Ironton Fire Brick C<br>Ironton, Ohio<br>Plant: Same address |
| ---------- | Laclede Super Plastic #333 | EN28/L5/3967 | Laclede Christy Compan<br>1711 Ambassador Bldg.<br>St. Louis, Mo.<br>Plant: Same address |
| ---------- | Super Mono-Fibrik | EN28/L5/3659 | Mexico Refractories Co.<br>Mexico, Missouri<br>Plant: Same address |



24 APR 1952

| Government Designation | Manufacturer's Designation | Test or Qualification Reference | Manufacturer's Name and Address |
|---|---|---|---|
| ---------- | Narco F-505 Super<br>Narco C-505 | EN28/L5/1873<br>EN28/L5/3513 | North American Refractories Company<br>National City Bank Bldg.<br>Cleveland 14, Ohio<br>Plants: Farber, Mo.<br>Curwensville, Pa. |
| ---------- | Plibrico K<br>Super Plibrico<br>Super Plibrico M | EN28/L5/3519<br>EN28/L5/3658<br>EN28/L5/1935 | Plibrico Jointless Fire Brick Company<br>1800 Kingsbury Street<br>Chicago 14, Ill.<br>Plants: Firebrick, Ohio<br>do.<br>Chicago, Ill. |
| ---------- | Super PCP | EN28/L5/1988 | Portsmouth Clay Products Company<br>Portsmouth, Ohio<br>Plant: S. Webster, Ohio |
| ---------- | Special Super Ramtite<br>do.<br>do.<br>Super Ramtite #22 | EN28/L5/1871<br>EN28/L5/3948<br>EN28/L5/4079<br>EN28/L5/4399 | The Ramtite Company<br>Division of S. Obermayer Co.<br>2563 W. 18th Street<br>Chicago, Ill.<br>Plants: Chicago, Ill.<br>Cincinnati, Ohio<br>Oak Hill Firebrick Co.<br>Oak Hill, Ohio |
| ---------- | Remmastics No. 3 | EN28/L5/1882 | Richard C. Remmey Sons Co.<br>Hedley & Delaware River<br>Philadelphia 37, Pa.<br>Plant: Same address |
| ---------- | Flint Patch | EN28/L5/3978 | The Robinson Clay Products Company<br>Second National Bank Bldg.<br>Akron 9, Ohio<br>Plant: Parral, Ohio |
| ---------- | Walsh Super Plastic Furnace Lining | EN28/L5/4371 | Walsh Refractories Corp.<br>4070 North First Street<br>St. Louis 7, Mo.<br>Plant: Vandalia, Mo. |