Waterfront Maintenance Note Number 6

Miniature/Micro-Miniature (2M) Electronic Assembly Repair Utilization

- Ref. (a) COMFLTFORCOMINST 4790.3 (JFMM)
 - (b) NAVSUP P485 Afloat Supply Procedures

Encl: (1) RMC 2M Support Request

- 1. <u>Purpose:</u> To establish procedures for requesting SERMC Miniature/Micro Miniature (2M) Electronic Assembly Repair.
- 2. <u>Background:</u> Virtually all Combat Systems and Engineering Plant equipment are listed in the Gold Disk database, which gives SERMC Code 953 the capability of repairing over 109,000 types of electronic modules and Circuit Card Assemblies (CCAs). 2M utilization is a "Front-line strategy" in cost avoidance, a top priority for the US Navy. Ship's force should aggressively submit all CCAs beyond ship's force repair capability to SERMC for repair.

3. Procedure:

- a. Ships screen all CCAs IAW shipboard 2M program IAW Ref (b). CCAs beyond economical repair must be submitted to SERMC Code 953 with the screening form.
- b. IAW Ref (b) Disposal at the shipboard level is not authorized for 3h and 3b cogs. If initial repair is unsuccessful, the SPY Phase Shift Driver (PSD) NIINs 01-555-8770 and 01-258-4223, must be turned in to the local RMC/IMA for repair and/or disposal.
- c. The ships EMO will be the single Point of Contact (P.O.C.) for all 2M work submitted to SERMC. The ships EMO must complete and sign Section 2 of the RMC 2M Support Request (Encl. 1) prior to submitting any component to SERMC for repair.
- d. Automatic Test Equipment (ATE) used at SERMC to troubleshoot failed CCAs is based on previously programmed data (Gold Disk Database). If no Gold Disk Database exits for the failed CCA, a known good card will be required to create a new database for that specific card. Once a database is created, future repairs to that type card will be possible using the Gold Disk Database.
- e. In order to minimize electrostatic discharge (ESD) damage to CCAs, proper handling procedures shall be followed to include transporting the items in ESD safe containers IAW Ref (a).
- 4. <u>Point of Contact:</u> For specific questions concerning SERMC capabilities, contact SERMC Mayport Code 953 at 904-270-5126 x3059, x3977, x5856 or x3115.



SERMC 2M SUPPORT REQUEST

FOR SERMC USE

SERMC_MYPT_2M@NAVY.MIL • 904-270-5126x3059

CUSTOMER SUPPORTING INF	ORMATION			D	ATE OF REQUES		oce o reacheann a da VAVI mandel engles en est e		
COMMAND WEE/EEE	i element		SYSTEM FOLLOWS:		KAT MA	enegari			
PHONE			APL		£(),188\$11	7PE			
POC THEE!	THE / PROPER		ASSY NAME		tina i	Ų			
			ASSY NSN		1264-401-400-05		COG		
JCN UK - WELLE CER	ren. Kanada		Y PART#_			SERIAL	·		
		TURN	I-IN COST_		eatemen				
	SHIP	BOARD 2M/N	ITR SUPPO	RT DATA					
JOB BRIEF / FAULTY INDICATION	ngsign	etro il de viki	MARKN TH	SEUS 703 E	e doge and fai	an sak	errows		
	<u></u>			·	****		242,-414		
	1900 to 100 to 1	Salatin salating	nia dia di						
LEVELS OF TROUBLESHOOTING COM	10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	UAL LIMTR	LI2M N	OTE: AND	१२०७, फ्रांस कालेक्स	ED 0x 04	The Atlantica and 1794		
GOLD DISK SUPPORTED NO	YES ROUT	INE ID:		ΑV	ALABLE TROUBLE	ATTOOHS	IG AIDS ATTACHED		
TROUBLESHOOTING PERFORMED	D BY:			The J	PRIME.		,		
	EMO AUTHOR	IZATION - CAS	REP AND R	EQUEST PI	RIORITY	•			
REPAIR WILL YES REPAIR R	REQUIRED		·	CASREP		*			
AVERT CASREP?	BY DATE:			CAT	DTG:	Set.	ENCAMBUR		
		-	` _		,		·		
					<u> </u>				
EMO PRINT	1		EMC	SIGN		ľ	DATE		
>>>>> FILL OUT FIELDS A									
	SOVE COMPLE	TELY, INCO	MPLETE P	REQUEST	S WILL NOT	SE ACC	EPTED <<<<	<u> </u>	
of the true post both and the resultance are expendent and the expension of the contract of th	SOVE COMPLE	TELY, INCC	MPLETE I					<< ※ ※	
RMC SUPPORT LOG	TTTELL	TELY, INCO			S WILL NOT I			<< 器器	
of the true policy and a company of the contract of the contra								~	
PELIVERED BY THE A PONY		, prop	OFF RECEIVED E (RMC)	Y 711	. ELEAD		CENTER 953	< ************************************	
DELIVERED BY (S/F) TROUBLESHOOTING		PROP- SCREEN GOLD DI	RECEIVED E (RMC)	Y	LE / PRINT		CENTER 953	<<	
DELIVERED BY (S/F) TROUBLESHOOTING COMPLETED:	MTR 2M	SCREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	Y	LE / PRINT	WORK	CENTER 953	< <	
POLIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES	MTR 2M	PROP- SCREEN GOLD DI	RECEIVED E (RMC) ING SK NC ED YES	Y	LE / PRINT	WORK	CENTER 953	V	
DELIVERED BY (S/F) TROUBLESHOOTING COMPLETED:	MTR 2M	SCREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	y ROU	LE / PRINT	WORK	CENTER 953	*	
POLIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES	MTR 2M	SCREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	y ROU	LE / PRINT	WORK	CENTER 953		
POLIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES	MTR 2M	SGREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	y ROU	LE / PRINT	WORK	CENTER 953	*	
POLIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES	MTR 2M	SCREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	ROU	LE / PRINT	WORK	CENTER 953		
DELIVERED BY STATE / POLIVE (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES COMMENTS:	MTR 2M	SGREEN GOLD DI SUPPORT	RECEIVED E (RMC) ING SK NC ED YES	ROU	LEAD	WORK	SON NOTED IN COMMENTS ITIONAL COMMENTS AND/OR ANTE ADDRIQUEM ATTACHED		
DELIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE TROUBLESHOOTING COMPLETE TROUBLESHOOTING COMPLETE TOYES	MTR 2M	SCREEN GOLD DI SUPPORT N NOTED IN COMMENT	RECEIVED E (RMC) ING SK NC ED YES	ROU	LEAD LE / SPINT TINE ID:	WORK	SON NOTED IN COMMENTS ITIONAL COMMENTS AND/OR ANTE ADDRIQUEM ATTACHED		
PELIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES COMMENTS: WORK PERFORMED BY	MTR ZM	SCREEN GOLD DI SUPPORT N NOTED IN COMMENT	RECEIVED E (RMC) ING SK NC ED YES REPAIRE	ROU	LEAD LE / SPINT TINE ID:	WORK	SON NOTED IN COMMENTS ITIONAL COMMENTS AND/OR ANTE ADDRIQUEM ATTACHED		
PELIVERED BY (S/F) TROUBLESHOOTING COMPLETED: TROUBLESHOOTING COMPLETE CYES COMMENTS: WORK PERFORMED BY	MTR ZM	SCREEN GOLD DI SUPPORT N NOTED IN COMMENT WAN HOURS //S 2M	RECEIVED E (RMC) ING SK NC ED YES REPAIRE	ROU	LEAD LE / SPINT TINE ID:	WORK	SON NOTED IN COMMENTS ITIONAL COMMENTS AND/OR ANTE ADDRIQUEM ATTACHED		
TROUBLESHOOTING VISUAL COMPLETED: TROUBLESHOOTING COMPLETE YES COMMENTS: WORK PERFORMED BY WORK PERFORMED BY	MTR ZM	SCREEN GOLD DI SUPPORT N NOTED IN COMMENT WAN HOURS //S 2M	RECEIVED E (RMC) ING SK NO ED YES S REPAIRE	ROU	TINE ID:	WORK	CENTER 953		



SERMC 2M SUPPORT REQUEST

SERMC_MYPT_2M@NAVY.MIL • 904-270-5126x3059

RMC SUPPORT LOG (CONTINUED) LEAD WORK CENTER 953										
RSN	PART#	COG	NSN	COST	COMPONENT STATUS			US		
					□ORD	□RCV	□он	□INS		
					□oŖD	□rcv	□он	□INS		
					□ord	□RCV	□он	□INS		
					□ORD	□RCV	□он	□INS		
					□ORD	□rcv	□он	□INS		
		-			□ORD	□RCV	□он	□INS		
					□ORD		□он	□INS		
					□ORD		□он	□INS		
					□ORD		□он	□INS		
	:				□ORD		□он	□INS		
					□ORĐ	□RCV	□он	□INS		
					□ORD		□oH	□INS		
					□ORD	□RCV	□он	□INS		
					□ORD	□RCV	□он	□INS		
					□ORD	□RCV	□он	□INS		
					□ORD	□RCV	□он	□ins		
				,	□ORD	□RCV	□он	□INS		
F+					□ORD	□RCV	□он	□INS		
					□ORD	□RCV	□он	□ins		
\$11					□ORD	□RCV	□он	□INS		
	<u> </u>				□ORD	□RCV	□он	□INS		
сомм	ENTS:									
					+-,		·			
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		·						
	•. •					· · · ·				
					,					
					1	,		٠.		
	•,			<u>s</u>				,		
*							•			
			••							
			•					Į		
·	Y		,							
	•		•	÷						
	•			-				ľ		