NAVSEA STANDARD ITEM

FY-16

ITEM NO:	009-112		
DATE:	18 JUL 2014		
CATEGORY:	I		

1. SCOPE:

1.1 Title: Prevention of Radiographic-Inspection Ionizing-Radiation Hazards; accomplish

2. REFERENCES:

2.1 None.

3. REQUIREMENTS:

3.1 This item applies to all contracts that utilize radiographic inspection as part of their work. "Foreign contractor" refers to a contractor that is contracted from the U.S. Navy host country in which U.S. Navy contracts may be executed onboard U.S. Government property and/or vessels.

3.2 Each foreign contractor shall comply with the regulatory standards of the host country when conducting radiographic inspections on U.S. Government property and/or vessels.

3.3 Fourteen days prior to start of work, submit one legible copy, in hard copy or approved transferrable media, of completed Radiography Operations Planning Work Sheet, Attachment A, to the SUPERVISOR and obtain approval prior to commencement of radiography operations.

3.4 Fourteen days prior to start of work, submit one legible copy, in hard copy or approved transferrable media, of a diagram illustrating the boundary where the exposure rate shall not exceed 2 mr/hr (0.02 mSv/hr) or under special circumstances the dose to an individual in any unrestricted area would not exceed 2 mrem (0.02mSv) in any one hour. In addition, the boundary shall meet the requirement that no individual member of the public will receive a dose in excess of 100 mrem (1mSv)in a calendar year from the radiographic work, exclusive of background radiation.

3.4.1 In addition to the boundary requirements of 3.4, the foreign contractor shall also illustrate the foreign radiation-boundary requirements.

3.5 Establish a physical boundary where the exposure rate is 2mr/hr or less. In some circumstances the boundary may be established at a point where the dose to an individual in any unrestricted area would not exceed 2 mrem in any one hour. The perimeter of the radiation area shall be a physical barrier

1 of 10

ITEM NO: 009-112 FY-16 established by an enclosure or by stanchions and rope, as necessary. Post this boundary with tri-foil radiation warning symbol, "Radiation Area", "Radiography in Progress", and "Keep Out" signs written in English and hostcountry language. The signs shall be visible to any person approaching the radiation area barrier from any accessible direction.

3.5.1 Radiographer shall maintain constant surveillance of the entire area boundary through direct observation or Radiation Safety Officer (RSO)/Radiation Safety Oversight Manager (RSOM) approved positive communication with boundary monitor who is in a position to provide visual surveillance.

3.5.2 Monitor the entire boundary using radiation detection equipment appropriate for the source of radiation during the first radiation exposure of the day. If the beam's orientation, kVp, mA, collimation, or shielding is changed between exposures, the boundary shall be re-surveyed and re-established in accordance with 3.5, if necessary.

3.5.2.1 Submit one legible copy, in hard copy or approved transferrable media, of a report listing results of the requirements of 3.5.2 within **one day**. The report shall include Attachment A diagram identifying survey locations, time, date and location of the survey, the highest radiation level recorded, the kVp, mA, and beam direction of the x-ray machine or, if using gamma source material, the half value of the collimator and beam direction at the time of exposure.

3.6 If an unauthorized individual crosses the boundary, the boundary monitor shall immediately notify the radiographer who will immediately stop radiography operations.

3.6.1 Report any boundary violation immediately to the SUPERVISOR. | Submit one legible copy, in hard copy or approved transferrable media, of a follow-up report within 4 hours of the violation, using Boundary Violation Report, Attachment B. The report shall include the time, date of violation, name of individual(s), the names of the radiography crew, including boundary monitor, the kVp, mA, duration of actual exposure and beam direction for the x-ray machine or if using source material, the half value of the collimator and the beam direction at the time of violation. Include a diagram showing the location of the violation and the egress path in relation to the source.

3.7 Upon discovery of loss or theft of radioactive material or x-ray producing devices, the radiographer shall cease and make safe all radiographic operations and immediately notify the SUPERVISOR.

3.7.1 Report verbally each incident *immediately* to the SUPERVISOR.

3.7.1.1 Submit one legible copy, in approved transferrable media, of a formal written report of the incident within **one day**.

4. <u>NOTES</u>:

4.1 The SUPERVISOR shall perform oversight and surveillance of all radiography operations on U.S. Government property and/or vessels associated with contracted work.

4.2 The technical point of contact for the requirements contained in this Standard Item is SUPERVISOR'S RSO or RSOM for radiographic inspections conducted in the host-country and any U.S. Government Detachment.

 $4.3\,$ This Standard Item complies with 10 CFR Parts 19, 20, and 34 and 29 CFR 1910.1096.

ATTACHMENT A

RADIOGRAPHY OPERATIONS PLANNING WORK SHEET

A.	General Information					
	1.	Prime Contractor Name:				
	2. Subcontractor Name (if applicable):					
	3. Proposed Date(s) and Time(s) of Planned Radiography:					
4. Purpose of Radiographic Operation:						
	5.	Host country regulatory standards applicable to radiographic inspections preferably translated to English.				
в.	If	conducting gamma radiography complete the following:				
	1.	Radioisotope: Serial Number:				
	2.	Activity: Date of Determination of Activity:				
	3.	Collimator Serial Number:				
	4.	Half Value Thickness:				
	5.	Transportation and vehicle information:				
		a. Manufacturer:				
		b. Model:				
		c. License Plate Number:				
		d. Sign on Vehicle:				
		e. Driver's Name:				
		f. Passengers:				
		<pre>g. Location of radiography operation site (ship, submarine, building pier):</pre>				

	h.	Transportation route to be taken to and from work site while on Government activity:
C.	<u>If co</u>	nducting x-ray radiography complete the following:
	1. Ma	chine Manufacturer:
	2. Se	rial Number:
	3. Ma	ximum kVp:
	4. Ma	ximum mA:
	5. То	tal Number of Exposures:
	6. Di	rection of Beam:
D.	<u>Provi</u>	de a diagram of each work site that illustrates:
	wa	ch location of the radiography, including major features such as lls, bulkheads, tanks, walkways or passageways that may provide ielding or difficulty in controlling the area.

- 2. The location of the exposure device drive cable, guide tube, and end stop if using gamma radiography equipment, or the location of the tube head and control panel if conducting x-ray radiography.
- 3. The location of the 2 mr/hr (0.02 mSv/hr) controlled boundary.
- E. Provide the calculations for the 2 mr/hr (0.02 mSv/hr) controlled boundary from the distance from the gamma radiography source, or the x-ray machine tube head, to the location where the boundary shall be established.

F. Review/Approval:

Signature

Date:

Date:

Signature

6 of 10 ITEM NO: <u>009-112</u> FY-16

BOUNDARY VIOLATION REPORT

Report

NAME OF REPORTING INDIVIDUAL:						
TIME/DATE OF THE VIOLATION:		COMPANY:				
LOCATION OF THE VIOLATION:						
FOI		SUPERVISOR:				
<u>FOR GAMMA RADIOGRAPHY:</u>	UIPMENI	<u>FOR X-RAY RADIOGRAPHY</u>				
		FOR A-RAT RADIOGRAPHT				
ISOTOPE:		<u>mA:</u>				
ACTIVITY:		<u>kVp:</u>				
HALF VALUE OF THE COLLIMATOR: DURATION OF EXPOSURE:		DURATION OF EXPOSURE:				
WORK ITEM NUMBER:		CONTRACT NUMBER:				
INDIVIDUALS W	HO VI	OLATED	THE BOUNDARY			
NAME(S)	D	EPT.	ORGANIZATION/COMPANY			
NAMES OF THE R	ADIO	GRAPHY	CREW MEMBERS,			
INCLUDING NAM	MES O	F BOUNI	DARY MONITORS			
NAME(S)	D	EPT.	COMPANY			

DESCRIPTION OF BOUNDARY VIOLATION

DIAGRAM SHOWING THE LOCATION OF THE VIOLATION AND THE EGRESS PATH IN RELATION TO THE SOURCE

SIGNATURE OF REPORTING INDIVIDUAL:	DATE:

Incident Report Instructions

REPORT NUMBER- Unique tracking number created by contractor

NAME OF REPORTING INDIVIDUAL: - Self Explanatory

DATE/TIME OF THE VIOLATION: – Self Explanatory

LOCATION OF THE VIOLATION: - Base/Yard, Ship name and hull number, space number and compartment name

COMPANY: - Prime and subcontractors involved

<u>SUPERVISOR</u> – Supervisor of employee(s) involved

<u>EQUIPMENT INVOLVED</u> – Self Explanatory

WORK ITEM NUMBER - Work Item being accomplished when incident occurred

CONTRACT NUMBER: - Contract Number assigned by government agency i.e. RMC, AIT Sponsor.

<u>INDIVIDUALS WHO VIOLATED THE BOUNDARY</u>: – Name, Department and Organization/Company of individuals that violated the boundary.

<u>NAMES OF THE RADIOGRAPHY CREW MEMBERS, INCLUDING NAMES OF BOUNDARY MONITORS</u>: – Name, Department and Company of the members of the radiography crew, including names of boundary monitors.

<u>DESCRIPTION OF BOUNDARY VIOLATION</u>: – Narrative description of the boundary violation including the sequence of events, time line, estimated exposures to individuals who violated the boundary, the immediate corrective actions taken to secure operations and emergency notifications that were made.

DIAGRAM SHOWING THE LOCATION OF THE VIOLATION AND THE EGRESS PATH IN RELATION TO THE SOURCE: -

A diagram of the location of the boundary violation showing the egress path and location of the individual(s) that violated the boundary, location of the source, beam direction (for x-ray machine radiography or gamma radiography if collimator was used) and the location of any barriers, walls, or equipment that would provide shielding.

SIGNATURE OF REPORTING INDIVIDUAL: - Self Explanatory.

 $\underline{\text{TITLE}}$ – Self Explanatory.

 \underline{DATE} – Self Explanatory.