<u>NAVSEA</u> STANDARD ITEM

FY-20

<u>ITEM NO: 009-92</u> <u>DATE: 30 APR 2018</u> <u>CATEGORY: II</u>

1. SCOPE:

1.1 Title: Resilient Mount; install

2. REFERENCES:

- 2.1 Standard Items
- 2.2 Equipment Technical Manual
- 2.3 S9073-A2-HBK-010, Installation and Inspection Information Resilient Mount Handbook

3. REQUIREMENTS:

- 3.1 Inspect for the presence of heavily mis-loaded or deformed mounts prior to mount removal using 2.2 and 2.3 for guidance.
- 3.1.1 Submit one legible copy, in approved transferrable media, of heavily mis-loaded or deformed mounts to the SUPERVISOR within 3 days of identifying the condition.
 - 3.2 Remove resilient mount assemblies, using 2.2 and 2.3 for guidance.
- 3.2.1 Inspect each equipment foundation for structural integrity, deterioration, pitting, cracks, and areas of damage or distortion.
- 3.2.1.1 Submit one legible copy, in approved transferrable media, of a report listing results of the requirements of 3.2.1 to the SUPERVISOR within 5 days after equipment removal.
- 3.2.2 Accomplishment of cleaning and painting for disturbed surfaces of each foundation where resilient mount assemblies have been removed shall be in accordance with NAVSEA Standard items (See Note 4.3).
- 3.3 Select, procure, assemble, install, load, and adjust new resilient mount assemblies including load bolts, foundation bolts, nuts, and snubbers in accordance with 2.3.

1 of 2 ITEM NO: $\frac{009-92}{\text{FY}-20}$

- 3.3.1 Stamp the installation date on each resilient mount flange adjacent to the identification date. The date shall be visible and legible when the mount is installed with 1/8-inch minimum lettering size.
- 3.3.2 Submit one legible copy, in approved transferrable media, of a report listing results of the requirements of 3.3 and 3.3.1 to the SUPERVISOR. The report shall include the following:
 - 3.3.2.1 Identity of equipment
 - 3.3.2.2 Amount and designation of mounts installed

4. NOTES:

- 4.1 Equipment technical manual and drawings referenced in invoking Work Item may identify mount designation and loading requirements.
 - 4.2 This item does not apply to turbine enclosure mounts.
- 4.3 If cleaning and painting for disturbed surfaces of each foundation where resilient mount assemblies have been removed of 3.2.2 is required; the use of Category II Standard Item 009-32 "Cleaning and Painting Requirements; accomplish" of 2.1 will be specified in the Work Item.

2 of 2 ITEM NO: $\underline{009-92}$