Waterfront Maintenance Note Number 2

Work Request Guidance

- 1. <u>Purpose</u>. To ensure ship's force personnel accurately complete work requests. SERMC Ship's Superintendent (SHIPSUP) can provide clarification for issues pertaining to this WFMN.
- 2. <u>Background</u>. Submitting accurate and concise 2-Kilos (2K) is paramount to ensuring that the work is executed as requested by the customer. Correctly completed 2Ks support the executing activity in documenting and tracking of work accomplished. Also, this ensures proper funding of waterfront accounts and manning requirements to accomplish the work.
- 3. The following guidelines are provided:

| Nomenclature | Quantity | Remarks |
|------------------------|--------------------------------|--|
| Accom ladders W/T or | One per 2k | S/F PMS 36M-1R |
| Inspection | One per 2k | Prerequisite. |
| A/C plants | One per 2k | |
| Awnings Structure only | One per 2k | Max size 25 x 20ft, per drawing, 2L, or sample |
| Baxter bolts | One per 2k | One per 2K if weld repair is required. Ten per 2K if chasing threads. One per 2K if manufacturing or weight bearing. |
| Boat davit repairs | One per 2k | S/F PMS Prerequisite |
| Boat davit weight test | One per 2k | |
| Brazer quals | Fiscal year job | Hard copy 2 Kilo in required for documentation |
| Casualty power cables | One 2k per casualty power rack | Length of each cable at rack |
| Chain hoists | One per 2k | |
| CIWS overhaul | One per 2k | |
| CIWS entrance unit | One per 2k | |
| CIWS exit unit | One per 2k | |
| CIWS transfer unit | One per 2k | |
| CIWS skip box | One per 2k | |
| Cold Lagging | Max 100 linear feet per job | Submit C940 Services Request Form via SHIPSUP |
| Conduit | One APL per 2k | |
| Condensers | One per 2k | |
| Coolers | One per 2k | |
| Deck drain replacement | One per 2k | Not for PMS (i.e. broken Screws) |
| Deck sockets | Ten per 2k | Note: For |

| | | manufacturing or weld |
|--|---|--|
| | | repairs one per 2K. |
| Deluge valves/hoses | Eight per 2k | Each module, hydro/mfg |
| Drip pans | Two per 2k | Same dimension on 2L |
| Engrave labels (small) | Fiscal year | i.e. valve labels |
| Engrave labels (large) | Fiscal year | Approx 8.5" x 11" |
| Flanges, blank | Five per 2k | List sizes in blk 35 |
| Flex hoses | Eight per 2k same system | Manufacture and hydro- Include hose material, hydro pressure, system fluid, overall length of hose, type(s) of fittings. |
| Flight deck pendants | Two per 2k | # Required for ship system |
| Flight deck safety nets and frames assembles | One 2k per system | Specify # per ship system for repair or W/T. Nylon web only. |
| Fuel oil injectors | Sixteen per 2k | |
| Gage calibration | One visit per 2k | Level 1 calibration assistance only |
| GTC/GTB/AYC/AYB | One GTE per 2k | One tech directive per 2K per engine, include GTM/GTG ser nr on 2K. |
| Heat exchangers | One per 2k | |
| HPAC/HPADS | One per 2k | |
| J-bar davit w/t | One per 2k | |
| Keys, duplicate | Ten per 2k | |
| Lifelines | Five Lines per 2k | Kevlar or cres; one 2K for Port or Stbd. |
| Life rails | Steel or Aluminum - Five sections per 2k | |
| Life rail stanchions | Steel - Two per 2k. | |
| Life raft harness/strap | Five per 2k | Manufacture/testing |
| Antenna repairs | One per 2k | |
| LPAC/LPADS | One per 2k | |
| Motor operated valves | One per 2k | |
| Motors (overhaul) | One per 2k | |
| Motor controllers | One per 2k | |
| Pumps | One per 2k | |
| P-100 pumps | One per 2k | |
| Reducing manifolds | One per 2k | Per capabilities manual |
| Relief valves >150 lbs | One per 2k | |
| Reefer compressor | One per 2k | Two 2K per job, one for Swap and one for overhaul. |
| Remote operators | One per 2k | |
| 2 | | |

| Refurb CAS srch ants | | |
|---|-----------------------------|---|
| VETUTO CAS STOIL GILLS | One per 2k | |
| Refurb CAS trck ants | One per 2k | |
| Refurb CAS radomes | One per 2k | |
| Refurb CAS waveguides | One per 2k | |
| Refurb stir antennas | One per 2k | |
| Refurb waveguides | One per 2k | |
| RIB | One per 2k | Include ser nr on 2K |
| Rigging services | One per 2k | Rigging services only |
| Safe repairs | One per 2k | |
| Sandblast/paint/ powder coat (SMALL) | Ten per 2k | Small items (less than 2 sq Ft). Must specify paint, or powder coat and approved std navy color. |
| Sandblast/paint/ powder coat (LARGE) | One per 2k | Large items (greater than 2 Sq ft). Must specify paint, or powder coat and approved std navy color. |
| ISUBA PACKS I | One repair locker per 2k | |
| LSCBA BOTTLE L | One repair locker per 2k | |
| I ESCADE SCRA | One repair locker per 2k | |
| Slings, wire rope, boat | Five per 2k | Mfg 1/8" to 1 1/8", dwg or 2L with material & swl |
| W/T Slings, non- ammo/ammo (wire rope) | Five per 2k | Same size, type, MK & mod |
| MK 105 Pendants for LSD/LPD/LHA | Up to Five per 2K | For testing, with serial numbers |
| MK 105 Legs for LSD/LPD/LHA | Up to Five per 2K | For testing, same color only orange or green with serial numbers |
| MK 105 Pendants for LSD/LPD/LHA | Up to Five per 2K | For testing of entire assembly. Pendant and four legs of the same color with serial numbers |
| Sounding tube caps | Ten per 2k | Same size/type |
| Stud installation | 5 min per space | |
| | | Location on 2L. One per |
| Stuffing tubes | One per 2k | 2K, if Weld repair is required |

| Torpedo breech mech | Three per 2k | Two jobs per Ship to cover stbd & port units. |
|---------------------|-----------------|--|
| Valves | One per 2k | Overhaul |
| Valve trailer | Fiscal year job | |
| WTD/WTS/FTD | One per 2k | |
| Weight testing | One per 2k | |
| Welder quals | Fiscal year job | Hard copy 2 Kilo in required for documentation. Welders required to bring their own equipment (hood, gloves, goggles, pgrinders and stinger) |

- 4. For equipment or services not listed in this maintenance note, submit a 4790/2K:
 - a. With only one associated APL. APL must be for the equipment to be repaired, not the next higher assembly.
 - b. With an approved DFS for manufacture of parts per sample where no drawing is available.
- 5. If in doubt about the number of items permitted on a 2K, or if there are any other questions, contact the applicable SERMC SHIPSUP prior to 2K Submission.
- 6. If there is a job that requires Technical Assistance (SERMC C200, previously known as FTSCLANT) and Production (SERMC C900, previously known as SIMA), a 2K must submitted for both. For example: Ship submits 2K for HPAC overhaul. Technical Assistance will use the one 2K to determine feasibility of this overhaul and make recommendations to the customer and Production. Upon completion of assessment, the ship shall submit another 2K to SERMC production, stating the recommendations and requesting completion of the overhaul based on those recommendations. The first 2K would be TA3 (tech assist) and the second TA2 (SERMC overhaul).
- 7. The key to the successful completion of any job is proper planning. The SERMC tech library is always available for use. It is imperative that the appropriate personnel are in contact with the SERMC production department planner during ship checks. This ensures the proper identification of required job specifications and scope.

SERMC CODE: 1200

Waterfront Maintenance Note #0 - Index

| WFMN Nr | TITLE | DATE UPDATED | LEAD DEPARTMENT |
|------------|--|-----------------|--------------------|
| 1 | RHIB Loaner Policy | 27 SEP 2011 | 900 |
| 2 | Work Request Guidance | 8 FEB 2023 | 900 |
| 3 | Boat Davit Assessment & Weight Test (Not issued at this time due to lack of capability. | N/A | 900 |
| 4 | SERMC Personnel Working Aloft | 27 SEP 2011 | 106 |
| 5 | Passive Countermeasures (PCMS) Readiness Improvement Program (RIP), & Maintenance, Repair & Replacement Procedures. Not issued at this time. | N/A | 200 |
| 6 | Miniature/Micro-Miniature (2M) Electronic Assembly Repair Utilization | 27 SEP 2011 | 900 |
| 7 | Documentation for Calibration of Test Measurement Diagnostics | 3 OCT 2011 | 200 |
| 8 | MK 38 Mod 1 Chain Gun System Installation | N/A | 900 |
| 9 | MK38 25mm Chain Gun and M242 Cannon Overhaul Procedure. | 23 Jan 2017 | 900 |
| 10 | AEGIS MK 99 Control System Collimation (Not issued at this time) | N/A | 200 |
| 11 | Magazine Sprinkler System Recertification Procedure (Not issued at this time) | N/A | 200 |
| 12 | Close-In Weapons System (CIWS) Gun Ammo Handling System (GAHS) Intermediate Level Overhaul Responsibilities | 1 AUG 2022 | 900 |
| 13 | MK 137 SRBOC Decoy Launching System Refurbishment | 27 SEP 2011 | 900 |
| 14 | Surface Vessel Torpedo Tube (SVTT) Intermediate Level Maintenance Responsibilities. | 27 SEP 2011 | 900 |
| 15 | MK 75 / 76 mm Gun ISMAT / ISMEP Procedure (Not issued at this time (On Hold) | N/A | 200 |
| 16 | Antenna Refurbishment Procedure | 27 SEP 2011 | 900 |
| 17 | Electromagnetic Compatibility (EMC) Survey Request Procedure | 7 OCT 2011 | 200 |
| 18 | MK 41 VLS Deluge System Water Treatment and Deluge Valve Overhaul | 27 SEP 2011 | 900 |
| 19 | Fleet Tech Assist (FTA) (Not issued at this time) | N/A | 200 |
| 20 | MK 41 Vertical Launch System (VLS) Cell Hatch Refurbishment and Replacement | 27 SEP 2011 | 900 |
| 21 | Relief Valve Testing Facility | 27 SEP 2016 | 900 |
| 22 | Emergency Breathing Air System Pressure Relief Valve Testing | 13 FEB 2018 | 900 |

Page | 1

SERMC CODE: 1200

| Cableway Assessment Gas Turbine Engine Layup Brow Gate Loaner Policy | 8 FEB 2023 22 NOV 2022 | 900 |
|--|---------------------------|-----|
| | 22 NOV 2022 | |
| 26 Brow Gate Loaner Policy | 22 140 4 2022 | 900 |
| | 2 FEB 2023 | 900 |
| 27 Cold Lagging Guidelines | 6FEB2023 | 900 |