

Waterfront Maintenance Note #0 - Index

WFMN	TITLE	UPDATED	DEPARTMENT
1	RHIB Loaner Policy	15 MAY 17	900
2	Work Request Guidance	25 MAY 17	900
3	Boat Davit Assessment & Weight Test (Not issued at this time due to lack of capability.)	N/A	900
4	SERMC Personnel Working Aloft	27 SEP 11	106
5	Passive Countermeasures (PCMS) Readiness Improvement Program (RIP), & Maintenance, Repair & Replacement Procedures. (Not issued at this time.)	14 OCT 11	200
6	Miniature/Micro-Miniature (2M) Electronic Assembly Repair Utilization	27 SEP 11	900
7	Documentation for Calibration of Test Measurement Diagnostics	3 OCT 11	200
8	No Longer Needed	N/A	900
9	MK38 25mm Mod 1 Chain Gun System , Removal and Overhaul	23 Jan 17	900
10	AEGIS MK 99 Control System Collimation	3 OCT 11	200
11	Magazine Sprinkler System Recertification Procedure	3 OCT 11	200
12	Close-In Weapons System (CIWS) Gun Ammo Handling System (GAHS) Intermediate Level Overhaul Responsibilities	27 SEP 11	900
13	MK 137 SRBOC Decoy Launching System Refurbishment	27 SEP 11	900
14	Surface Vessel Torpedo Tube (SVTT) Intermediate Level Maintenance Responsibilities.	27 SEP 11	900
15	MK 75 / 76 mm Gun ISMAT / ISMEP Procedure	3 OCT 11	200
16	Antenna Refurbishment Procedure	27 SEP 11	900
17	Electromagnetic Compatibility (EMC) Survey Request Procedure	7 OCT 11	200
18	MK 41 VLS Deluge System Water Treatment and Deluge Valve Overhaul	27 SEP 11	900
19	Fleet Tech Assist (FTA) (Not issued at this time)	N/A	200
20	MK 41 Vertical Launch System (VLS) Cell Hatch Refurbishment and Replacement (On Hold for Capability Evaluation)	N/A	900
21	Relief Valve Testing Facility	23 MAY 17	900
22	Emergency Breathing Air System Relief Valve Testing	13 FEB 18	900
23	Operating Procedures	5 NOV 18	900