



31 AUG 2018

From: Director, NAVSEA Standard Specification for Ship Repair and Alteration Committee (SSRAC)

Subj: FISCAL YEAR 2019 CH-4 NAVSEA STANDARD ITEMS

Ref: (a) COMUSFLTFORCOMINST 4790.3

(b) NAVSEAINST 9070.1

1. Per references (a) and (b), the Fiscal Year 2019 (FY19 CH-4) NAVSEA Standard Items (NSI) are available on the official SSRAC Web site at:

<http://www.navsea.navy.mil/Home/RMC/CNRMC/OurPrograms/SSRAC.aspx>

2. The FY-19 **CH-4** NSIs are effective for availabilities in which FY-19 standard Items are invoked. FY19 availabilities that are not at the 100% of D Level Maintenance Work Package Lock Milestone shall be re-planned to incorporate FY19 **CH-4** NSIs listed. FY19 **CH-4** NSIs shall supersede all related CSWTs, SWTs, and LWTs.

FY-19 CH-04 NSIs Affected:

- 009-72 Physical Security at a Private Contractor Facility; accomplish
- 009-06 Maintaining Protection and Cleanliness from Non-Radioactive Operations; accomplish
- 009-08 Shipboard Fire Protection and Fire Prevention; accomplish
- 009-13 Meter, Gage, Switch, and Thermometer; repair
- 009-17 Rotating Electrical Equipment; repair
- 009-33 Rotating Electrical Equipment; rewind
- 009-36 Controller; repair
- 009-45 Tapered Plug Valve; repair
- 009-46 Butterfly Valve, Synthetic and Metal Seated; repair
- 009-47 Gate Valve; repair
- 009-48 Pressure Seal Bonnet Valve Shop Repair; accomplish
- 009-49 Pressure Seal Bonnet Valve In-line Repair; accomplish
- 009-50 Horizontal Swing Check Valve; repair
- 009-52 Relief Valve; repair
- 009-53 Bolted Bonnet, Globe, Globe Angle, and Globe Stop Check Valve Shop Repair; accomplish



- 009-54 Bolted Bonnet, Globe, Globe Angle, and Globe Stop Check Valve In-line Repair; accomplish
- 009-55 Regulating/Reducing Valve; repair
- 009-71 Piping System; test
- 009-75 Circuit Breaker; repair
- 009-81 Compartment Closeout; accomplish
- 009-96 Ball Valve; repair
- 009-113 Rotating Electrical Equipment with a Sealed Insulation System (SIS); rewind
- 009-117 Combat Systems Light-Off Support; provide

3. SSRAC/RMC Coordinators are responsible for advising users within their command of this notice. Code 400 Contracts Department is responsible for advising Master Ship Repair (MSR) Contractors and Agreement for Boat Repair (ABR) Contractors under their cognizance of the availability of these products.

4. The requirements of this letter do not authorize any change in terms, conditions, delivery schedule, price, or amount of any Government contract. In the event you consider the requirements represent a change for which an equitable adjustment is in order, you are to advise the Contracting Officer of the particular technical or contractual requirements regarded as changed, and take no action with regard to such changed requirements until notified in writing of the Contracting Officer's response.

5. Point of Contact for further information is Mr. Dale Hirschman, Technical Director, 757-400-0020, dale.hirschman@navy.mil.



Dale Hirschman

Distribution:
SSRAC E-Mail